RENTON ENVIRONMENTAL LABORATORY REPORT

HAZARDOUS WASTE REPORT

Lab Id: 00-B564 Field Id No.: PL2SA-1854 #462

Field Notes: NBF Catch basin

Analyte		Result	Units	Method #	Analyst	Date	Status
OTHER TESTS:	PCB:	1.03	ma/Ka	8080	KSC	7/18/00	

Report prepared by:

Report approved by:

Date: 7/18

Date: 7/18/09